


Using a bit whose diameter equals the

Drill...

Wedge Anchor

anchor diameter, drill hole. to any depth exceeding min imum embedment. Clean hole. Drive....



and washer so that top of nut is flush with top of anchor. Drive anchor. through material to be fastened so that nut and washer is flush with. surface of material.





3 to 5 turns, or tothe specified torque requirement.